JON R O'HARE 17479 7TH AVE SW NORMANDY PARK, WA 98166

Re: Project #6698208-DM-004

Correction Notice #1

Review Type GEO SOILS Project Address 801 3RD AVE

SEATTLE, WA 98104

Contact Email JON@PERMITCNW.COM

SDCI Reviewer Pao Huang **Reviewer Phone** (206) 684-5825

Reviewer Email pao.huang@seattle.gov

Owner D LLC

Date April 08, 2021 **Contact Phone** (425) 301-9541

Address Seattle Department of Construction and

700 Fifth Ave Suite 2000 PO Box 34019

Inspections

Seattle, WA 98124-4019

Description of Work:

Revision: Install temporary rubble bracing, per plan.

Reference:

March 12, 2021 "Geotechnical Recommendations for Rubble Berm Support of Basement Wall ", by Hart Crowser (File No. 19567-01)

Document Reviewed:

Plan Set uploaded on 3/25/2021 (1.26 MB)

Applicant Instructions

You will not be able to upload corrected plans until all reviews are completed and the project's review status is "Corrections Required".

*** Respond by providing a written response to each correction AND identify changes to drawings since initial review. ***

Drawings shall be **legible**, with sheets **oriented correctly**, on an appropriate **sheet size**, with all revisions/changes **clouded or circled**, with **no missing sheets**, and uploaded in a **single PDF file**.

Link for detailed steps: "How to Respond to a Correction Notice". If the 3-step process outlined in this document is not followed, your response could be **rejected**, permit issuance could be **delayed**, and **penalty fees** could be assessed.

Codes Reviewed

This project has been reviewed for conformance with one or more of the following codes: 2015 Seattle Building Code (SBC); 2015 Seattle Residential Code (SRC); 2015 Seattle Existing Building Code (SEBC); 2015 Seattle Energy Code (SEC); Grading Code; Environmentally Critical Areas Regulations (ECA).

Project #6698208-DM-004, Correction Notice #1

This project has been reviewed for conformance with one or more of the following codes: 2018 Seattle Building Code (SBC); 2018 Seattle Residential Code (SRC); 2018 Seattle Existing Building Code (SEBC); 2018 Seattle Energy Code (SEC); Grading Code; Environmentally Critical Areas Regulations (ECA).

Corrections

- 1. The bench width is 6 feet. Please have geotechnical engineer confirm Kp=4.1 used by the structure engineer is appropriate. Please also elaborate on how the Kp is developed for the slopped ground with a bench as recommended in the Table 1 in the Memo.
- **2.** Please have geotechnical engineer recommend monitoring program for the basement wall deflection during demolishing and the monitoring program should be included in the plans.
- **3.** SMC 22.170.190 A. Provide a signed and stamped letter from the geotechnical engineer that includes review of the plans and provides a minimal risk statement in accordance with Director's Rule 5-2016. The plan review/minimal risk letter must be based upon review of plans with all substantial geotechnical recommendations incorporated.
- **4.** SMC 25.09.080 D and 22.170.080 A.1. Liability insurance, including Products Completed Operations Coverage, is required by the ECA and Grading Codes. Contact Amber Udelhoven of City Risk Management at amber.udelhoven@seattle.gov to facilitate submittal of insurance forms from the contractor's insurance agent. Be prepared to provide the names of the excavation and shoring contractors
- **5.** SMC 22.170.130. Nominate a geotechnical engineering firm on the enclosed SDCI Geotechnical Special Inspections Schedule form. This form must be signed by the owner or owner's representative; the form cannot be signed by the contractor nor the geotechnical engineer.

The Inspection Agency must be the same engineer/firm that prepared the geotechnical report. If the owner nominates a different engineer/firm to act as the Geotechnical Special Inspector, the new engineer must review the original geotechnical report and submit a letter indicating a review was performed, along with a statement of agreement with the evaluation and provisions contained in the report. If the new engineer does not agree with aspects of the report, rebuttal evaluations and recommendations must be included in the review letter. The plans must be revised accordingly and submitted to SDCI for review. Please do not fill in special inspection items on the enclosed form.

Requests for changes of Special Inspection Agency that occur during plan review should be submitted with corrected plans. If the request occurs after permit issuance, send the materials to jerry.abson@seattle.gov.

Revised Schedule	Addition to	Previous Schedule	7		
SDCI Geotechnica		_	e		
Project Number 6698208-	OM-004		Da	ate 4/8/2021 6:15 PM	
Project Address 801 3RD AVE SEATTLE, WA 98104			SDCI Plan Pao Huang Examiner		
Architect			Architect Pho	ne	
Engineer			Engineer Phone		
Property Owner or Owner's Agent Signal hereby certify that the geotechnical enginelow as required by the Seattle Building Conspection agency in a timely manner where	eer named belo Code. It is the re	sponsibility of the owne	er or the owner's o		
ignature	Title	Date		Phone	
ART CROWSER INC		206-324-9530			
eotechnical Engineering Firm Name		Geotechnical Engineering Firm Phone			
Required Special Inspections					
Inspection Type		Description			
1. Observe And Monitor Excavation					
2. Other Geotechnical		Monitor deflection of	Monitor deflection of basement wall		
Call (206) 684-8860 to schedule	e a pre-cons	truction conference	e before the	start of construction	